



Pressure Legend Raw

1000	2
992	0
985	2
978	1
971	1
964	2
957	0
950	3
942	0
935	0
928	1
921	1
914	2
907	0
900	0
892	1
885	8
878	10
871	10
864	9
857	19
850	27
842	27
835	26
828	23
821	24
814	25
807	40
800	46
792	52
785	48
778	58
771	60
764	57
757	66
750	97
742	91
735	92
728	111
721	106
714	101
707	153
700	157
692	177
685	164
678	196
671	179
664	220
657	208
650	247
642	252
635	206
628	177
621	177
614	133
607	117
600	126
592	105
585	96
578	83
571	84
564	74
557	80
550	99
0	60777

550 - 1000

Comments

Disc #2

See "Subject Image Window" for an image of the disc.

Dot is facing DOWN (ie - The side WITH the Dot is being measured)

1520 N applied at Frame 36

Group 1 (Red) is the Dot Location  
 Group 2 (Blue) is the Arrow Location  
 Group 3 (Green) is the location of the Numerical Indicators

Recommended Lower Threshold Setting: 550  
 Recommended Upper Threshold Setting: 1200

Non-functional Lines in Sensor: Rows 126 through 129 and Column 158

General All Frames Frame 36 Attributes



Statistics

	Avg Pres.	Peak Pres.	Area (cm <sup>2</sup> )
Pad 1(256,256 : 50000)	677,73	1082,0	62,94
Dot Location	726,84	779,0	0,33
Arrow Location	0,0	0,0	0,00
Numerical Indicators	0,0	0,0	0,00